Theo/T. Kennedy

WETLAND RESTORATION

(PHASE I - final report)

PROJECT HISTORY

The development of the area in question began June 23, 1986, when an application for a permit to construct a 40.19 acre project known as Gahagan Plantation was submitted to the SCDHEC-OCRM. On July 29, 1986 a project certification was granted by the SCDHEC-OCRM; this project called for the use of a 372,416 cubic foot detention basin, formed by excavating an area adjacent to the Sawmill Branch, in Summerville, SC.

Work on this project began in late 1986, and continued during the entire 1987 year. On March 9, 1987, applications were submitted for approval for two other projects in the same general area. These projects were known as Gahagan Plantation II and Garbon Subdivision. This marked the beginning in a change in thinking that was designed to save wetlands and to use wetlands to improve water quality. The practice of excavating wetlands to create detention ponds would no longer be considered as a suitable design. Special protection would be constructed to preserve the wetlands, while the storm water runoff would serve to replentish nutrients to the wetlands. The natural filtering would improve water quality down stream.

The new plan was incorporated in the original Gahagan Plantation design, and no wetlands were destroyed to create detention ponds. The existing wetlands were used on a larger scale to control storm water runoff. It was learned that the cost of the extra protection measures used to guard the erosion of the wetlands, would in fact cost no more than it would have cost to create the typical detention pond. There was the possibility that the final cost would be less in most cases.

The new project area was increased to 144.67 acres, consisting of Gahagan Plantation I,
Gahagan Plantation II, a portion of Gahagan Road, and Garbon Subdivision. The existing
wetland that was utilized ,was formed when Sawmill Branch was constructed as one of the main
drainage canals serving Summerville, SC as a storm water structure for the Town. The area

used was approximately 7.5 acres, and had an operating level of 41.5 feet msl. This area would detain 467,400 cubic feet of stormwater, with an additional capacity of 178,450 cubic feet available to the minimum height of the retaining berm. (Elevation 42 feet msl.) The 100 year flood elevation is 43 feet (plus or minus) msl, and is a function of the backwater from the Ashley River, and the flow in Sawmill Branch. From this information, it was recognized that detaining the 100 year storm would not be possible, since the waters affecting the wetlands area would be originating from offsite sources.

The analysis of the project was made for a 25 year storm frequency. Having a 60 minute time of concentration, and an intensity of 3.7 inches per hour, the site was calculated to have a preconstruction coefficient of runoff of .35, and a post-construction weighted coefficient of runoff of .548. The required storm water detention was calculated to be 425,590 cubic feet, which gave 41,810 cubic feet of storage surplus, below the 41.5 foot msl elevation.

FACTORS AFFECTING ORIGINAL PROJECT

The combined project was greatly affected by two occurrences that changed the manner of how the wetlands would be affected. First, the owner of the project suffered a drastic change in financial fortune based on factors outside of the immediate concern of the project. This changed the relationship of the owner to the project, since the project was secured by lending institutions as payment of other debts. Secondly, the entire wetlands management plan was placed in doubt when a storm occurred while Sanitary Sewer work had the main ditch system blocked. This caused the berm system to be breached, depositing a substancial amount of erosion silt into Sawmill Branch. The owner was in no position to remedy the problem, and the Town of Summerville stepped in and secured the berm. The means used to secure the berm released a majority of the storm water directly to the Sawmill Branch as a least cost emergency fix to the problem. During the time after this occurred, attention was diverted to other more immediate

concerns caused by Hurricane Hugo. During the years after Hugo, it was discovered that the wetlands were drying up.

WORK of the RESTORATION PROJECT

Through the efforts of the SCDHEC - OCRM, and the Charleston Harbor Project, a program to correct the effects of past events concerning this development was initiated. With the corrections in place, water quality would be improved to the levels once sought for the area.

Initial investigation made two facts obvious. The wetlands were drying up because two of the outlet pipes beneath the retaining berm had been layed too low. Also, in order to manage water quality, the effects of the emergency fix provided by the Town of Summerville, SC would have to be changed.

The first measure taken was to control all runoff from frequent rainfall so that it entered the wetland area where filtering could occur. This was accomplished by installing a diverter structure that controlled all flow in the system that occurred below elevation 41.0 msl. This measure also assured that all of the wetlands would be fed a supporting source of moisture on a regular basis. The system would divert all stormwater from the first inch of rainfall, and capture the first flush conditions that would occur, and allow these conditions to be filtered. Secondly, the existing outlet beneath the berms were changed by additional pipe structures so that the lost of water could be controlled. This was done in a manner that would be compatible with the previous design for stormwater management. The additional design provides a means of maintaining a pool elevation of 39.0 feet msl which is the original beginning point for storage of stormwater detention. This level is adjustable should future findings deem such adjustment to be desired. The redesigned system allows filtering action between the elevations of 36 feet and 41.2 feet msl. Freguently occurring stormwater levels can be effectly treated without

accumulating amounts that would cause concern in the surrounding areas. This restoration project has been conducted with special thought given to ensure that the system would continue to function when storms of unusual magnatude occur. It was recognized that the majority of water quality issues are affected by storms that frequently occurr, and will have the greatest effect for storms giving a little as one half inch of runoff.

Submitted By

Thomas W. Kennedy, Jr., P.E. & L.S.

Thomas W. Kennedy, Jr., P.E. & L.S.

Consulting Engineer • Land Surveyor • General Contractor

September 3, 1996

Mr. J. Heyward Robinson Charleston Harbor Project SCDHEC - OCRM 1362 McMillan Ave., Suite 400 Charleston, SC 29405

Re: CHP Project 319 - 1.0

Dear Mr. Robinson:

In response to your inquiry regarding the level of rainfall needed to produce a discharge from the wetland detention area, I have determined that too many factors are related to determining this event, to make a call.

The presents of the Sawmill Branch so near to the area, produces a natural loss of ground water at a rate that cannot be determined with any accuracy. The diverter structure releases runoff with respect to the depth of flow reaching the structure, therefore the magnatude and duration of the storm event could have varying results regarding discharge from the system. Since the system has been installed, there has been no discharge from the system. The true volume of detention is in question below the 39.0 feet msl level. The volume below this level was not used in calculating the effects of the 25 year storm event because it was known to be affected by irregular ground conditions that may have not been picked up by topographic survey.

As I understand, sampling of the system discharge must be scheduled in advance. I regret that I am not in a position to aid in making this schedule. I would recommend that an automatic sampling device be developed for this purpose. I would be available to aid in developing such a system if my aid would be helpful. If I can be of further assistance with this project please call.

Sincerely.

Thomas W. Kennedy, Jr., P.E.& L.S.

encl:

ASHLEY RIVER STORMWATER WETLAND RESTORATION PROJECT

PHASE I GAHAGAN SUBDIVISION

SUMMERVILLE, SOUTH CAROLINA


NDEX


26 26(1.3)


CHETTER CRANGE STRUCTURE SEE PLAN (MEST SECTION) STR PLAN (BAST SECTION)



TRICO ENVIROMETRICS INC. 4055 FABER PLACE DRIVE, SUITE 201 NORTH CHARLESTON, SOUTH CAROLINA 29405 (803) 740-7700







CP IE MT ALM


T 68" 20


SECTION D-8

MOVE

I. ALL CHE TO BE RETALLED HIST BE SHOOT BONE, PLLLY BETANNOUS CONTED FRE MORRY AMERICAN CLENET CORP. BUT-405 SHAPE J 'A' OR EDUAL

(AMISTO ASIA THPE II IN AASHTO MINO THPE A.)






SIE PLAN (EAST SECTION)

Concrete Diverter Structure





BASELINE MONITORING OF VEGETATION TRANSECTS FOR THE SAWMILL BRANCH

WETLAND RESTORATION PROJECT

to monitor long-term biological changes in the wetland vegetation community as a result of the restored hydrology conducted by

USACOE in conjunction with SCDHEC/OCRM on May 23, 1996

Gahagan Subdivision Wetland Restoration Project

Charleston Harbor Project Special Project

Description of existing conditions and dominant vegetation

A site inspection was performed at the above referenced site on May 23, 1996. This inspection and assessment were performed by Jeff Thompson of OCRM and Jake Duncan of USACOE. The findings are as follows.

The project site is a remnant wetland community associated with Sawmill Branch, a channelized stream system in Dorchester County, South Carolina. This wetland has experienced significant modification due to channelization of the stream system. Hydrology has been reduced and the vegetative community is likely to experience long term changes in species distribution. Restoration activities performed at this site should enhance hydrology and reduce the likelihood of long term vegetative community changes. The existing community is bottomland hardwood with distinct canopy, subcanopy, shrub, and herbaceous layers.

Canopy species: Gordonia Iasianthus, Acer rubrum, Quercus Iarifolia, Leriodendrun tulipifera, Ilex opaca, Liqidambar styraciflua, and Pinus elliotteii.

Sub-canpopy: Ligustrum sinense, Magnolia virginiana.

Shrubs: Lucothoe axillaris, Lyonia lucida, Itea virginica, Persea borbonea, Simplocus tinctoria, and Vibumum dentatum.

Ferns: Osmunda regalis, Osmunda cinnomenea, Woodwardia areolata, and Thelipterus sp.

Vines: Rhus radicans, Smilax rotondifolia, Smilax glaucus, Decumeria barbara, Berchemia scandens, Vitus estavalis, Lonicera japonica, Parthinocisous quinqifolia, and Vitus vulpina.

Relic stumps and knees of bald cypress were noted. It would be anticipated that cypress may return as hydrology is increases by the restoration activities.

Appendix A

Summary of Storm Water Detention Calculations

PRE DEVELOPMENT RUNOFF VALUES

| AREA T.C. I COE RUNOFF | 144.67 USE 60 3.70 : 0.35 | AC MIN. SEE GAHAGA 25 YEAR STORM | N I PLANS | |
|---|------------------------------------|--|-----------|--------------|
| PRE DEV. Q = C. PRE DEV. Q = (0 PRE DEV. Q = 18 | .35)(144.67) 7.35 CFS | | | |
| AREA | 144.67 | AC. | | |
| COE. | 0.548 | ~. | | |
| GAHAGAN I | ACRES | PERCENTAGE | COE | EQUALS |
| SUBDIVISION | 13.32 | 0.09 | .50 | .45 |
| COMMERCIAL | 3.90 | 0.03 | .95 | .029 |
| CHURCH | 3.00 | 0.02 | .95 | .019 |
| SCHOOL | 12.00 | 0.08 | .95 | .076 |
| ROAD | 1.20 | 0.01 | .50 | .005 |
| POND | 3.20 | 0.02 | .95 | .019 |
| MISC. | 1.64 | 0.01 | .30 | .003 |
| SUB TOTAL | 38.26 | 7.02 | .50 | •003 |
| GAHAGAN II | | | | |
| SUBDIVISION | 19.32 | 0.13 | •50 | .050 |
| GARBON SUBDIVISION | | | | |
| SUBDIVISION | 85.27 | 0.59 | .50 | .29 5 |

GRAND TOTAL 144.67 AC

__1.82

GAHAGAN ROAD

1200 LF S 66FT

0.01

.65

.007

0.548

Appendix A (Continued)

| DURATION (MIN.) | RAINFALL (25 YR) INCHES | RUNOFF RATE (A)(C)(I) | RUNOFF VOLUME (CFS)(DUR) (60) | OUTFALL VOLUME (Q PRE)(DUR) (60) | DIFFERENCE |
|--------------------|-------------------------------|-----------------------------|--|---|------------------|
| 5 10 | 8.3 7.2 | 658.02 570.81 | 197406 | 56205 | 141201 |
| 15 | 6.5 | 515.31 | 342486 463779 | 112410 168615 | 230076 295164 |
| 20 25 | 5.9 5.5 | 467.74 436.04 | 561288 654060 | 224820 280025 | 336468 374035 |
| 30 35 | 5.1 4.8 | 404.32 380.54 | 727776 799134 | 337230 393435 | 390546 405699 |
| 40 45 | 4.4 | 364.68 340.90 | 875232 | 449640 | 425592 |
| 50 | 4.0 | 317.12 | 920430 951360 | 505845 562050 | 414585 389310 |
| 55 60 | 3.8 3.6 | 301.26 285.40 | 994158 1027440 | 618255 674460 | 375903 352980 |

THE MASS CURVE METHOD ABOVE INDICATES A MAXIMUM DIFFERENCE IN STORM WATER RUNOFF BETWEEN EXISTING AND POST DEVELOPMENT CONDITIONS OCCURS AT A 25 YEAR FREQUENCY STORM OF A 40 MINUTE DURATION, AT APPROXIMATELY 425,592 C.F.S. THEREFORE THE DETENTION REQUIRED FOR THIS PROJECT IS 425600 C.F. WHEN THE ENTIRE 144.67 ACRES ARE DEVELOPED.

EXISTING DETENTION VOLUME IN WETLANDS AREAS

1. AREA OF ELEVATION 39.0 = 7000 S.f. AREA OF ELEVATION 40.00 = 161000 S.f.

VOLUME BETWEEN ELEVATION 39.00 & 40.00 [7000 S.F. + 16100 S.F.] X 1 FT. DEEP = 84000 C.F.

2. AREA OF ELEVATION 40.0 = 161000 S.F. AREA OF ELEVATION 41.0 = 335000 S.F.

VOLUME BETWEEN ELEVATION 40.0 & 41.0 [161000 S.F. + 335000 S.F.] X 1 FT. DEEP = 248000 C.F.

VOLUME BELOW 41.0 + 332000 C.F.

3. AREA OF ELEVATION 41.0 = 335000 S.F. AREA OF ELEVATION 41.5 = 394000 S.F.

VOLUME BETWEEN ELEVATION 41.0 & 41.5 [335000 S.F. + 394000] X .5 FT. DEEP = 182250 C.F.

VOLUME BELOW 41.5 = 514250 C.F. VOLUME REQUIRED = 425590 C.F.

DIFFERENCE SURPLUS [88660]
STORAGE

4. AREA OF ELEVATION 42.0 483000 S.F. AREA OF ELEVATION 41.5 394000 S.F.

VOLUME BETWEEN ELEVATION 41.5 & 42.0 [483000 S.F. + 394000] X .5 FT. DEEP = 219250 C.F.

VOLUME BELOW ELEVATION 42.0 = 733500 C.F. TOP OF BERM

OUTFALL PIPE DESIGN

li i iir

PRE DEVELOPMENT RUNOFF 187.35 CFS

PIPE NO. 164 24" Ø RCP 50.00 CFS PIPE NO. 189 24" Ø RCP 50.00 CFS PIPE NO. 192 18" Ø RCP 30.00 CFS PIPE NO. 194 18" Ø RCP 34.00 CFS PIPE NO. 195 15" Ø RCP 23.00 CFS


| Sawmill Branch (Dorchester Creek) | | | | | |
|---|---------|---------|---------|---------|---------|
| Date | 1/13/95 | 1/13/95 | 1/13/95 | 1/13/95 | 1/13/95 |
| Time | 1940 | 2025 | 2055 | 2250 | 2335 |
| Flow (Q= x cubic feet/second) | 50.8 | 130 | 160 | 175 | 217 |
| 1 10W (42 × 64516 1663566614) | | | | | |
| Water Temperature, degrees Celsius | 15.4 | 16.5 | 16.5 | 16.2 | 16.9 |
| Barometric Pressure (mm of HG) | 760 | 760 | 768 | 760 | 760 |
| Rainfall accumulated (inches) | 0.33 | 1.09 | 1.11 | 1.13 | 1.14 |
| Specific Cond., microsiemens/cm @ 25 deg. C. | 168 | 154 | 163 | 144 | 150 |
| Oxygen dissolved, (mg/L) | 9.4 | 9.4 | 9 | 8.5 | 8.8 |
| Biochemical Oxygen Demand, 5-day @ 20 deg. C (mg/L) | 1.8 | 2.9 | 2.9 | 3.9 | 2.4 |
| pH, Water, Whole, Field, Standard Units | 7.9 | 7.7 | 7.7 | 7.6 | 7.6 |
| pH, water, whole, laboratory, standard units | 7.2 | 7.2 | 7 | 7.1 | 7.1 |
| Nitrogen Ammonia, dissolved (mg/L as N) | 0.04 | 0.04 | 0.04 | 0.03 | 0.03 |
| Nitrogen Ammonia plus organic total (mg/L as N) | 0.5 | 0.4 | 0.5 | 0.9 | 0.6 |
| Phosphorous total (mg/l as P) | 0.07 | 0.09 | 0.18 | 0.46 | 0.41 |
| Phosphorous Orthophosphate, dissolved (mg/l as P) | 0.04 | 0.06 | 0.12 | 0.09 | 0.07 |
| Phosphorous, Hydrolizable plus Ortho total (mg/l as P) | 0.05 | 0.18 | 0.57 | 0.62 | 0.4 |
| Calcium, dissolved (mg/L as Ca) | 18 | 20 | 21 | 20 | 16 |
| Magnesium, dissolved (mg/L as Mg) | 1.5 | 1.3 | 1.2 | 1.2 | 1.2 |
| Sodium, dissolved (mg/L as Na) | 9.5 | 7.7 | 6.1 | 6.9 | 7 |
| Poatssium, dissolved (mg/L as K) | 0.9 | 0.7 | 0.9 | 1.3 | 1 |
| Chloride, dissolved (mg/L as Cl) | 13 | 10 | 9.5 | 8.2 | 8.9 |
| Silica, dissolved (mg/L as SIO2) | 6.3 | 5.2 | 4.4 | 4.1 | 5.4 |
| Barium, dissolved (mg/L as Ba) | 19 | 15 | 13 | 13 | 16 |
| Beryllium, dissolved (mg/L as Be) | 0.5 | 0.5 | 0.5 | 0.5 | 0.5 |
| Cadmium, dissolved (ug/L as Cd) | 10 | 10 | 10 | 10 | 10 |
| Chromium, dissolved (ug/L as Cr) | 1 | 1 | 1 | 1 | 1 |
| Copper, dissolved (ug/L as Cu) | 10 | 10 | 10 | 10 | 10 |
| Iron, dissolved (ug/L as Fe) | 430 | 310 | 190 | 290 | 350 |
| Lead, dissolved (ug/L as Pb) | 100 | 100 | 100 | 100 | 100 |
| Manganese, dissolved (ug/L as Mn) | 15 | 17 | 16 | 18 | 13 |
| Molybdenum, dissolved (ug/L as Mb) | 1 | 1 | 1 | 1 | 1 |
| Stronium, dissolved (ug/L as Sr) | 47 | 46 | 51 | 43 | 38 |
| Zinc, dissolved (ug/L as Zn) | 10 | 12 | 5 | 13 | 9 |
| Lithium, dissolved (ug/L as Li) | 4 | 5 | 5 | 5 | 5 |
| Fecal Coliform, .7 UM-MF (Col./100mL) | 5600 | 6600 | 12000 | 11000 | 5600 |
| Density (gm/mL @ 20 deg. C.) | 0.998 | 0.998 | 0.998 | 0.998 | 0.999 |
| Mercury, dissolved (ug/L as Hg) | 0.2 | 0.1 | 0.2 | 0.1 | 0.1 |
| Specific Conductance, microsiemens/cm @ 25 deg. C | 154 | 154 | 168 | 149 | 128 |
| Alkalinity, titration to pH 4.5, Laboratory (mg/L as CACO3) | 43 | 43 | 54 | 49 | 38 |

IT

Results for wetlands pre-restoration sampling event Gahagen subdivision, Summervile, SC October 31, 1995

| Sample number | SSB1 | SSB2 | CCD3 | | | |
|------------------------------|-------|---------------|-------|-------|------|-------|
| Time (FOT) | | 03 D Z | SSB3 | SSB4 | SSB5 | SSB6 |
| Time (EST) | 1115 | 1200 | 1240 | 1325 | 1410 | 1616 |
| Rain (inches) | trace | 0.06 | 0.15 | 0.19 | | 1615 |
| Discharge (cfs) | 0.16 | | | 0.19 | 0.21 | 0.22 |
| • • | 0.16 | 0.92 | 1.50 | 0.58 | 0.21 | 0.17 |
| H | 8.01 | 7.83 | 8.79 | 7.60 | 7.59 | |
| emperature (°C) | 18.5 | 18.8 | 10.6 | | 7.39 | 7.57 |
| pecific conductance (µS) | | | 19.6 | 19.2 | 19.3 | 19.4 |
| " • | 164 | 183 | 112 | 108 | 139 | 166 |
| issolved oxygen (mg/L) | 9.2 | 8.8 | 8.0 | 8.2 | | |
| spended sediment (mg/L) | 15 | 122 | | | 8.2 | 8.2 |
| md/Silt split | | 122 | 896 | 269 | 136 | 37 |
| 6 finer than 0.062 mm sieve) | 86.8 | 68.0 | 86.5 | 87.0 | 66.8 | 87.8 |
| etal suspended solids (mg/L) | 7.5 | 160.8 | 831.2 | 220.6 | | |
| | | · · · | 051.2 | 239.6 | 41.4 | 114.7 |

Water-Quality Sample, Pre Restoration, 10/31/95



Suspended sediment (mg/L)
Total suspended solids (mg/L)